



Tel: 952-888-1816  
 Web: [www.tegraseal.com](http://www.tegraseal.com)

### INSTALLATION COVERING OBTUSE ANGLED CORNER

Details: WOOD LAGGING DETAIL	
Date Issued: 03/29/2010	
Scale: NONE	Drawing No.: 0702-23